

Subject: Malfunction Indicator Light (MIL) ON, DTC P0421 or P0431 Stored in DTC Memory

Model(s): allroad quattro with 2.7L (Eng. Code APB 2001 and ECM Part No. as listed below) Group: 01 Number: 03–05 Date: May 5, 2003

Supersedes T.B. Repair group 01 No. 03-03 dated Apr. 17, 2002 due to incorrect date only

Condition

ECM requires "Update - Programming" (flashing) to correct:

MIL is ON with Diagnostic Trouble Code (DTC) P0421 "Warm up catalyst, bank 1, efficiency below threshold", or DTC P0431 "Warm up catalyst, bank 2, efficiency below threshold" stored in DTC memory.

The Engine Control Module (ECM) may diagnose the Warm up Catalytic Converter incorrectly under high engine load conditions. The diagnosis threshold has been changed in MY 2002 Engine Control Modules (ECM).

Applies only to 2001 allroad quattro models with ECM Part No: 4Z7 907 551 or Part No: 4Z7 907 551K.

Service

CAUTION!

The following "Update - Programming" (flashing) process may overwrite any "TUNED" ECM programming.

A "TUNED" ECM is described as any ECM altered so as to perform outside the normal parameters and specifications approved by Audi of America, Inc..



1 of 12 plus attachments



If you encounter a vehicle with a "Tuned" ECM, prior to performing the "Update -Programming" (flashing) procedure:

- Your Dealership should place the vehicle owner on notice in writing, that their ECM was found to have been tuned, and that any damage caused by the tuning of the ECM (including any adverse emissions consequences) will not be covered by Audi of America, Inc. warranties.
- For any repair requested by the owner under warranty or outside warranty that requires flashing, which will automatically wipe out the "Tuning" program, your Dealership should advise the owner of the above and get his written consent (see attached Control Module Tuning form) to the flashing procedure.

Tool requirements

- ♦ VAS 5051 or VAS 5052 with Basis CD A.05.15 and the Brand CD A.05.0 (or later).
- "Update Programming" (flashing) CD "KM01" (indicated on CD).

Additional copies of "Update - Programming" (flashing) CD (Item no: A0050012588) may be ordered from the Audi Technical Literature Ordering Center at audi.ddsltd.com, or by calling 1-800-544-8021 from 8:00 a.m. to 8:00 p.m. EST Monday through Friday. This number can be dialed in both the United States and Canada.



2 of 12 plus attachments



Vehicle requirements

- Battery MUST have minimum no-load charge of 12.5V (failure to maintain voltage during update process can lead to ECM failure)
- VAS 5051: connected to vehicle (using K-lead adapter VAS6017A) and to 110V AC Power supply at all times during procedure
- VAS 5052: connected to vehicle (using K-lead adapter VAS6017A) with battery voltage requirements met
- Any appliances with high electromagnetic radiation (i.e. mobile phones) switched OFF.
- No stored DTCs, print and erase any stored DTCs.

CAUTION!

Non–observance of the following points may lead to ECM failure!

VAS 5051 or 5052 must always be connected to the approved power supply at the approved voltages. Under no circumstances should the power supply be interrupted or the diagnostic connector unplugged during the flash procedure.

Any appliances with high electromagnetic radiation (i.e. mobile phones) must be switched OFF.

C 01-03-05

3 of 12 plus attachments

AUOI Important! AUOI Please give copies to all your Audi Technicians

> PRIOR to performing procedure to "Update - Programming" (flash) the ECM:

- ALL fault memories must be interrogated and erased.
- Switch ignition ON.
- Select Vehicle "Self Diagnosis mode".
- Select Diagnosis function 00 "Collection services".
- Select "Check DTC memory complete system" which will interrogate all fault memories.
- Print all DTCs.
- Erase ALL fault memories.

Once ALL fault memories have been erased:

"Update - Programming" CD must be used to place the tester into the flashing mode (see "VAS 5051 / VAS 5052, programming for flashing mode" below).

 Update Programming (reflash) the Engine Control Module (ECM). Do not replace catalytic converter.

VAS 5051 / VAS 5052, programming for flashing mode

- Switch ignition ON.
- Switch VAS 5051/5052 ON and insert flash CD into CD drive as soon as start screen appears.
 - Select "Applications".



<u>C 01–03–05</u>

4 of 12 plus attachments

© 2003 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Vehicle

VAS 5051

Vehicle Diagnostic, Testing and Information System Version -USA/CDN- /V03.13 20/08/2002



C 01-03-05

5 of 12 plus attachments

Important!

Please give copies to all your Audi Technicians

Audi

Technical Bulletin

Vehicle Self-Diagnosis	01 - Engine electronics			
	ECM Part Number			
Select	ECM description & software level			
diagnosis function	Coding XXXXX			
	Dealership number XXXXX			
02 - Interrogate fault memory				
03 - Final control diagnosis				
04 - Basic settings				
05 - Erase fault memory				
06 - End output				
07 - Code control unit				
08 - Read data block				
09 - Reading individual measuring value				
10 - Adaption				
11 - Log-in procedure				
Update - Programming				
Go to Instruments	Print Help			
	01-4133			
	01-A133			

Vehicle Self-Diagnosis	01 - Engine electronics			
Update - Programming	ECM Part Number			
	ECM description & software level			
	Coding XXXXX			
Programming can be carried out.	Dealership number XXXXX			
WARNING!				
The programme version stored in the control unit will be erased				
It will be programmed with the new version 000X				

The erasing programming process will last roughly XX minutes The part number in the control unit identification may change. Vehicle specific data (coding, adaptation etc.) might be lost. It must be checked after successful programming

After the continue button has been pressed the process cannot be cancelled.

IMPORTANT -- PLEASE NOTE:

Switching ignition off or disconnecting the diagnostic connector during programming may completely destroy the control module!



"Update - Programming" (flashing) procedure, checking for update match

- On the Applications screen, select the button, to return to start screen.
- Select "Vehicle Self Diagnosis" mode.
- Select vehicle system "01-Engine electronics".
- Select the "Print", then "Screen" button.
- − Select the button.
- "Update Programming" (arrow) will appear.

Note:

The "Update - Programming" function is only available when the inserted flash CD level and current vehicle ECM level are different.

 Select "Update - Programming" option at bottom of screen (arrow).

CAUTION!

Once "Update - Programming" function has been started, switching ignition OFF or disconnecting the diagnostic connector may completely destroy the ECM.

"Update - Programming" (flashing), performing

After selecting "Update - Programming" function:

- ♦ New program version and approximate timing for update is shown on the VAS 5051/5052 screen.
 - By selecting the ▶ button, the programming procedure begins.

C 01-03-05

6 of 12 plus attachments

Important! Please give copies to Technical Bulletin Αυδι all your Audi Technicians Vehicle Self-Diagnosis 01 - Engine electronics Update - Programming ECM Part Number Similar screen appears. ECM description & software level Programming in progress Coding XXXXX Dealership number XXXXX The previous data in the ECM is erased and Data Transfer in % the new data is being transferred to the module from the flash CD. 100 Note: Approx. flash time is 17-19 minutes. 01-A137 Vehicle Self-Diagnosis 01 - Engine electronics Update - Programming ECM Part Number NOTE: ECM description & software level Programming in progress Coding XXXXX Dealership number XXXXX If, during the "Update - Programming", a fault Data Transferred in % message is displayed:

100

01-A138

Cancel

- Confirm that VAS 5051 or VAS 5052 diagnostic tool power supply is adequate and that ALL appliances with high electromagnetic radiation (i.e. mobile phones) are switched OFF.
- The "Update Programming" (flashing) process must then be started from the beginning using the "Repeat" button (arrow).
 DO NOT use the "Cancel" button.

Important!

On NO occasion should the "Cancel" button be selected or the ignition switched OFF.



C 01-03-05

Diagnosis bus faulty

Repeat

No voltage or voltage too low on diagnostic bus

Is the battery voltage from the vehicle too low?

Is the diagnostic connector connected to the vehicle?

7 of 12 plus attachments

AUGI Important! AUGI Please give copies to all your Audi Technicians

Vehicle Self-Diagnosis	01 - Engine electronics				
Update - Programming	ECM Part Number				
Programming log	ECM description & software level				
Save result?	Dealership number XXXXX				
Expanded identification old	Expanded identification new				
XXXXXXXXXX	XXXXXXXXXX				
Description and software level	000				
Coding xxxxx Dealership number xxxxx	Dealership number xxxxx				
Unit number 942 Unit number 0 Importer number 444					
Programming status					
Status No malfunction					
Counter programming status	1				
Counter successful attempts	pts 1				
Programming pre-condition fulfilled					
Go to	Print Help				
	01-A144				

Once "Update Programming" (flashing) is complete:

- ♦ Similar screen appears.
- Old ECM Part No. and software level are still displayed at (arrows).

Note:

New ECM Part No. and software level are not displayed until process is complete and fault memories have been erased.

- Select the "Print", then "Screen" button.
- ◆ VAS 5051 will print to printer immediately.
- VAS 5052 will hold the print until process is complete and then you may take the tester to the printer for printing the screen.
- Attach print to vehicle Repair Order.

Once "Update - Programming" (flashing) is complete, the control module must be re-initialized.

- Select the button.
- The tester requests you to switch the ignition OFF.
 - Switch ignition OFF.

IMPORTANT!

 Wait at least 20 seconds before switching the ignition back ON (failure to wait at least 20 seconds may damage the ECM)

After waiting 20 seconds:

- Switch ignition ON.

After switching ignition ON, the ECM has been re-initialized, however, fault memories must be now be erased.

- Select the "Continue" button.

8 of 12 plus attachments

 Vehicle Self-Diagnosis
 01 - Engine electronics

 Update - Programming
 ECM Part Number

 ECM description & software level
 Image: Comparison of the control unit requires an ignition off/on cycle

 To continue, the control unit requires an ignition off/on cycle
 Image: Comparison of the comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cycle

 Image: Comparison of the cycle
 Image: Comparison of the cyc

C 01-03-05

Auði Please all you	Dortant! e give copies to ur Audi Technicians	echnical Bulletin				
Vehicle Self-Diagnosis	01 Engine electronice	ו				
Update - Programming Erase fault memory	UI - Engine electronics ECM Part Number ECM description & software level Coding XXXXX Dealership number XXXXX	Fault memories, erasing after "Update - Programming" (flashing)				
The programming causes fault records in related control units. The fault memories of all control units in the vehicle must be erased. Pressing the Continue button will automatically erase the fault memories.		 Due to the CAN bus system, fault messages will be stored in various Control Modules during programming. ■ To erase ALL fault memories, confirm by selecting the button. 				
Go to Print Help		<i>Erase fault memories takes approx. 15 minutes.</i> Once fault memories have been erased:				
Vehicle Self-Diagnosis Update Programming DTC memories are erased Function ended Vehicle systems with erased fault 01 - Engine electronics 02 - Gearbox electronics 03 - Brake electronics 15 - Airbag 25 - Immobilizer	01 - Engine electronics ECM Part Number ECM description & software level Coding XXXXX Dealership number XXXXX memories:	 Similar screen appears. Old ECM Part No. and update version of software level still appear at (arrows). Function ended appears at bottom of screen. 				
16 - Steering wheel electronics 46 - Convenience system central module 56 - Radio 17 - Dash panel insert Function ended! Test Test Test Test Go to Print Help 01-A145		Finish update of ECM by selecting the				
Vehicle Self-Diagnosis Vehicle system with a number of control units	01 - Engine electronics ECM Part Number ECM description & software level Coding XXXXX Dealership number XXXXX	 Similar screen appears. New ECM Part No. 477 907 551M will 				

- New ECM Part No. 4Z7 907 551M will appear.
- ◆ Udate version software will appear.
- Print the ECM screen to verify ECM update software level.

VAS 5051 / VAS 5052 MUST now be returned to "Normal" operating mode as follows:

9 of 12 plus attachments

- Select "Go to" then "Exit".

C 01-03-05

Test Instruments Go to

Print

Help

01-A159

XXXXXXXXXXXXX

XXXXX XXXXXXXXXXXXXXXXX



Audi Please give copies to all your Audi Technicians	echnical Bulletin
VAS 5051 is now set back to it's original mode	 The VAS 5051/VAS 5052 is now set back to it's "original mode". Select "OK". Note: If this step is not completed the VAS 5051/VAS 5052 will NOT be capable of performing any diagnostic functions!
ок 01- А154	
Applications Application selected AESIS Start application from CD-ROM Service Traning	 On the Applications screen, select the button, to return to start screen. ECM reprogramming is complete. Note: It is not generally necessary to encode the ECM following the "update - Programming" (flashing procedure. However, you must set the readiness code. To set readiness code:
01-A172	• Use VAS 5051 or VAS 5052 and Self Diagnosis, along with the attached Quick Reference "How to set Readiness Code".

With readiness code set:

 Remove CD and disconnect VAS 5051 / VAS 5052 from vehicle.

For Warranty information see Page 12.

C 01-03-05

11 of 12 plus attachments



all your Audi Technicians

Please give copies to Technical Bulletin

When procedure applies to vehicles with- in the New Vehicle Limited Warranty:				
W2				
2470 39 xxx1				
Due to the varying complexity of tester software and vehicle systems checked by the tester, actual time may vary, therefore A-Time must be used.				
24709999				
Maximum A-Time allowed 130 TU				
Type "As Per Technical in comment section of				

*) xxx = Vendor code for part



12 of 12 plus attachments



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULES(S)

*) "TUNING" is described as the addition of or modification of any component which causes an Audi vehicle to perform outside the normal parameters and specifications approved by Audi of America, Inc..

Date:	

Dealer Number:

Vehicle Identification Number:

Repair Order Number:

 	••••	

Dealer stamp

I _____, owner or driver of the above identified Audi, confirm:

☐ "Tuning" as described above (especially power increasing modifications) has NOT been performed on my vehicle.

☐ "Tuning" as described above has been performed on my vehicle and the following components were modified or installed:

<u>TUNING was performed by (Please provide Company name and telephone number, if you wish us to contact them):</u>

I understand that if my Control Module is determined to have been tuned, any damage caused by the tuning of the Control Module (including adverse emissions consequences) will not be covered by Audi of America, Inc. warranties.

I am requesting that my Dealer reflash (update) my Control Module, and understand that this process will automatically (overwrite) and permanently wipe out any "Tuning" program which was previously performed on the Control Module.

I have read this statement and confirm my request by affixing my signature immediately below.

Signature of Customer



Quick Reference: How to set Readiness Code



S4/A6/Allroad 2.7T BiT, engine code APB, MY 2000-2002 TLEV

	Procedure VAS 5051/ 5052						
Step	Diagnostic Status	Engine	Function/	Channel	Channel	Channel	Channel
		Condition	Display-Group	1	2	3	4
1	Check DTC Memory	Engine OFF	02	-	-	-	-
2	Clear DTC Memory	Ignition ON	05				
3	Adaptation Throttle Valve	Engine OFF	04/060	3% - 20%	80 - 97%	8	ADP.OK
	Control Module	Ignition ON					
4	Adaptation Kick Down	Engine OFF	04/063	-	78 - 94%	Kick Down	ADP.OK
	(Only with Automatic Transmission)	Ignition ON					
		Press gas pedal to the floor					
5	Fuel System Leakage	Engine ON @ Idle	04/071	-	-	Check	Syst. OK
	Check					END	
6	EVAP Canister Purge Regulator	Engine ON @ Idle	04/070	0% - 100 %	-	-	EVAP OK
	Valve Check						
7	Lambda Control	Engine ON @ Idle	04/107	640 – 920	-18 - +18%	-18 - +18%	Syst. OK
				RPM			
8	Heated Oxygen Sensor	Engine ON	04/041	0 - 0.5 kOhm	Htg.bC ON	0 - 0.5 kOhm	Htg.aC ON
9		1800 - 2200/min*	04/042				
10	Operational Readiness of	Engine ON @ Idle	04/036	0-1V	B1-S2 OK	0-1V	B2-S2 OK
	Oxygen Sen. behind Cat. Conv.						
11	Response Time Front Heated	Engine ON	04/034	1520 - 2280	more than	0,4 - 1,0 s	B1-S1 OK
12	Oxygen Sensor	1520 - 2280/min**	04/035	RPM**	260°C		B2-S1 OK
13	Oxygen Sensor Control System	Engine ON @ Idle	04/037	0 - 30 %	0 - 1 V	-150 - +150 ms	Syst. OK
14			04/038				
15	Oxygen Sensor aging	Engine ON @ Idle	04/043	700 - 3000	more than	0 – 1 V	B1-S2 OK
16	behind Cat. Conv.		04/044	U/min	350°C		B2-S2 OK
17	Three Way Catalytic Converter	Engine ON	04/046	1880 - 2280	more than	0 - 0.80	CAT B1 OK
18		1880 - 2280/min**	04/047	RPM**	315°C		CAT B2 OK
19	Secondary Air System	Engine ON @ Idle	04/077	$\overline{640 - 920}$	0-5 g/s	-40 - +10 %	Syst. OK
20	Only AT vehicles	_	04/078	RPM	_		-
21	Check Readiness Code Setting	Engine ON @ Idle	08/086	00000000	0000000	00000000	00000000
	6						

Requirement: Coolant Temperature more than 80°C

* to warm up engine if necessary, test is complete when values are present in channel 1 and 3 ** only during Diagnostic Performance For more details, refer to Repair Manual "Readiness Code, generating". Confirm Readiness Code generating with a VAS 5051 Printout!