

menu: : MAIN : FEATURES : EVENTS : QUARTER MILE RACING : VW TECH : FORUMS AND CLASSIFIEDS : LINKS : CONTACT



chapters.indigo.ca

VW Tech



Tuesday, Nov. 14, 2006



Materials:

- Belt Sander (not necessary but it would save you a bunch of time)
- Hand Sander
- Sand paper grits: 40-60-80-120-220-320-420-600-800-1000-1500-2000
- Sanding Block
- WD-40
- Duct Tape
- Rubbing Compound
- Blue Magic Compound
- Mask
- Lots of time and patience

VW TECH BY: vr6power

STEP 1.



After removing the manifold. Use the duct tape to cover all the holes on the manifold, runners etc.

Start with the 40 grit and leave the surface as smooth as possible.

STEP 2.



It should look like this.. (3 runners on the left).

STEP 3.



After the surface is completely smooth (be careful not to leave any dark spots) You can start with the hand sander from 60 - 420.

STEP 4.



600 - 2000 grit is going to be wet sanding you can use water but WD-40 does wonders.

STEP 5.



At 1000 grit. After the 1500 grit you're going to start seeing the results.

STEP 6.

After you're done with the 2000 wet sand, clean the surface with some WD-40 and some paper towels.

Then you can start with the rubbing compound, repeat this process 4-8 times.

Start applying the blue magic compound, you'll start seeing that baby shining like a mofo.

ALL DONE!



