



Important!

Please give copies to
all your Audi Technicians

Technical Bulletin

Subject: **Engine Oil, Capacities**

Group: **17**

Number: **01-02**

Model(s): **All Audi Models**

2000, 2001

Date: **Mar. 22, 2001**

Supersedes T.B. Group 17 Number 01-01 dated Feb. 5, 2001 due to corrected APB spec.

Vehicle	Engine	Filter change	Capacity*
A4/S4	ATW 1.8 L Turbo	w/ Filter	3.7 qt / 3.5 L
	AWM 1.8 L Turbo	w/ Filter	3.7 qt / 3.5 L
	APB 2.7 L Biturbo	w/ Filter	6.9 qt / 6.5 L
	AHA 2.8 L	w/ Filter	6.0 qt / 5.7 L
	ATQ 2.8 L	w/ Filter	6.0 qt / 5.7 L
A6	APB 2.7 L Biturbo	w/ Filter	6.9 qt / 6.5 L
	AHA 2.8 L	w/ Filter	6.0 qt / 5.7 L
	ATQ 2.8 L	w/ Filter	6.0 qt / 5.7 L
	ART 4.2 L	w/ Filter	8.0 qt / 7.6 L
	AWN 4.2 L	w/ Filter	8.0 qt / 7.6 L
allroad quattro	APB 2.7 L Biturbo	w/ Filter	6.9 qt / 6.5 L
A8/S8	AKB 4.2 L	w/ Filter	7.6 qt / 7.2 L
	AUX 4.2 L	w/ Filter	7.6 qt / 7.2 L
	AYS 4.2 L	w/ Filter	7.6 qt / 7.2 L
TT	ATC 1.8 L Turbo	w/ Filter	4.8 qt / 4.5 L
	AWP 1.8 L Turbo	w/ Filter	4.8 qt / 4.5 L
	AMU 1.8 L Turbo	w/ Filter	4.8 qt / 4.5 L

*) Quantities listed are approximate. DO NOT OVER-FILL! Overfilling engine oil can cause misfire DTC's to be stored in Engine Control Module (ECM) -J220-.

To prevent overfilling at oil changes, add approx. 0.5L less than capacity, start engine, let run until engine operating temperature is approx 60°C (140°F), turn OFF ignition, wait approx. 3 minutes, check dipstick, fill to MAX.

C 17-01-02